To: Mahler, Tom[mahler.tom@epa.gov]

From: Estep, Rebecca

Sent: Fri 12/23/2016 6:53:39 PM **Subject:** RE: Bridgeton Dust QAPP

2420 4G.pdf

See attached COC SOP.

Rebecca Estep

U.S. Environmental Protection Agency – Region 7

Quality Assurance Specialist

11201 Renner Blvd. Lenexa, KS 66219

(913) 551-7598

estep.rebecca@epa.gov

From: Mahler, Tom

Sent: Friday, December 23, 2016 12:22 PM **To:** Estep, Rebecca < Estep. Rebecca @epa.gov >

Cc: Tapp, Joshua Tapia, Cecilia Tapia, Cecilia@epa.gov; Harris, Diane <a href="mailto:E. E. Yapia.Cecilia@epa.gov; Jackson, Robert <a href="mailto:V. Yapia.Cecilia@epa.gov; Juett,

Lynn <Juett.Lynn@epa.gov> **Subject:** Bridgeton Dust QAPP

My start contractor and I just finished going over our changes to the QAPP based on our discussion yesterday. I will be sending a new pdf and a word doc with track changes in the next 10 to 15 minutes.

I believe we were able to address all of your comments. I suspect we will need to discuss the reference to EPA Region 7 COC procedures and section 4.2 in regards to trip blanks.

Other than that, I think you find everything in the QAPP that we discussed.

Our intent is to use the original signature page that I sent yesterday unless you tell me otherwise
My contractor is standing by should he need to round people up for a new signature page today.
Talk to you soon,
Tom Mahler
On-Scene Coordinator
US EPA Region 7
816-604-0546